

USACE, Galveston District

Observer(s) On Duty: _____

Date: 2 / 18 / 95

Additional Comments: considered 100% overflow screened, with partial inflow
sampling. The Ouachita captain and Gulf Coast personnel were very cooperative
in making improvements to the inflow screening. Before load 134 was finished
new screening was added to the forward lander to prevent debris from flowing
over the top of the existing screen. Debris can still flow over the inflow
screening of the mid and aft landers.

Observers will be taking water temperatures daily from the dredge
in the cut area.

